

**Improvement Opportunities Frequency Rate (IOFR)** the Current Rolling IOFR is: **1.38**  
(Target of 2.5 per 1000 hours worked)

**Accident Frequency Rate (AFR)** Days since the Last RIDDOR accident: **298**  
The current rolling AFR is: **0.03**

**Service Strike (SSFR)** Days since the last Service Strike: **2**  
The current rolling SSFR is: **0.38**

**April**  
**Total Number IOs**  
**305**

**April**  
**No. Safety, Health & Environmental IOs**  
**N/A**

**April**  
**No. Business IOs**  
**N/A**

Reference Number	Business unit	Date	Project	Description
<b>Injury</b>				
INC-000048	Highways	08/04/2024	EHA Kings Lynn Nora	Operative suffered irritation when some concrete from a concrete pump contacted his leg whilst he was cleaning it
INC-000050	Highways	22/04/2024	NH SDF Wentbridge Viaduct	Whist water jetting a catch pit, an operative suffered a bruised hand
<b>Service Strike - Water</b>				
INC-000052	Highways	23/04/2024	Lord Street Joints and Waterproofing	Valve on water main has been damaged by excavator
<b>Service Strike - Gas</b>				
INC-000058	Highways	18/03/2024	Monks Farm	Valve cover was removed during excavations, gas was smelt so asset owner was called to investigate
<b>High Potential Near Miss/Close Call</b>				
INC-000046	Rail	02/04/2024	OTW GEO Gillingham Tunnel Refurbishment	RCM removed too early resulting in trains being stopped
<b>TM Incursion</b>				
INC-000051	Highways	18/04/2024	NH SDF M18 j13-14	Two vehicles followed works vehicles into closure, stopped and escorted out
INC-000053	Highways	23/04/2024	NH SDF MG Gathurst	Wide load drove through works and knocked over cones, cones reinstated
INC-000054	Highways	27/04/2024	NH SDF M56 Beechwood	Drunk driver with damaged vehicle, pulled up to and was held at airlock attempting to exit motorway. Police called.
<b>Theft</b>				
INC-000055	Rail	29/04/2024	Essex AfA	A surveying scanner tripod has been stolen. It was left outside the front of the station.
<b>Property Damage</b>				
INC-000056	Highways	25/04/2024	Connect Plus Harlington High St Concrete Repairs	Theft and fire (arson) from within site stores outside of working hours
<b>Other Classification</b>				

INC-000059	Rail	03/04/2024	OTW GEO RCM Monitoring	Ecologist sustained a tick bite, unclear if it happened in connection with Octavius works
INC-000049	Highways	11/04/2024	Monks Farm	Member of public was in a dangerous position taking photos of works, asked to remove themselves from the carriageway
INC-000057	Highways	11/04/2024	A140 Long Stratton Bypass	Member of public was flying a drone over the site at low level, he became abusive when asked to stop